

CERTIFICATE


1. It is certified that fwg bldgs have been inspected and found structural safety.

- (a) T-111
- (b) P-112
- (c) T-113
- (d) T-141
- (e) T-142
- (f) 173/C
- (g) 174/C
- (h) T-130
- (j) T-131
- (k) T-42
- (l) P-123

2. Next insp will be carried out subsequently.

Station : c/o 56 APO

Dated : 07 Dec 2019


(Bhola Tiwari, IDSE)
EE
GE (South) Patiala